Work Order ID 91264

91264

Page 1

. 4.4

Item ID: 647.0112 Accept *N900040100* Setup Start **Revision ID:** Item Name: Strut Bracket **Start Date:** 10/04/12 **Start Qty: 98.00** *98* **Cust Item ID:** Required Date: 10/31/12 Req'd Qty: 98.00 **Customer:** Reference: Run Process Plan: MU5 Date: 12-10-05 Tooling: Approvals: Date: Stop OC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Reject Accept Reject Insp. Work Center ID Description **Run Hours** Code Qty **Qty** Number Stamp **Draw Nbr Revision Nbr** 647.0100 Α 100 0.00 FLOW WATER JET *100* 100 0 JM 12-10-13 Waterjet 0.00 Memo FLOW CNC Waterjet 1-Cut as per Dwg 304.080 Dwg Rev:_ Prog Rev: 2-Deburr if necessary 110 QC2- Inspect parts off machine FAI/FAIB 0.00 *110* 100 OC 0.00 Memo **Quality Control**

* Work Order ID 91264 October-05-12 9:11:56 AM				*91264*									Page 2		
Item ID: Revision ID: Item Name: Start Date: Required Date:	647.0112 Strut Bracket 10/04/12 10/31/12	Start Qty: 98.00 Req'd Qty: 98.00		*98* *98*	Accept	Cus	Item	∩4∩ ^{ID:}	100)* s	etup Star Stop	i V	S1* S2*	Ξ	
Approvals:	Process Pla	in:	Date:		Tooling: SPC (Y/N):			ate:		R	un Star Stop	!	R1* R2*		
Sequence ID/ Work Center II 120 *120* QC Quality Control)	Operation Description QC8- Inspect parts - secon	nd check		Set Up/ Run Hours 0.00 Smb 0.00 12 0		ol ID	Tool #	Plan Code	Accept Qty ICT COlin	Reject Qty	Reject Number	Insp. Stamp	-	
130 *130* Brake NC Brake NC		Form as per dwg NC BRAKE Memo			0.00			· · · · · · · · · · · · · · · · · · ·		 			Jm1309	ì-25	
140 *140* QC Quality Control		QC5- Inspect part complet Memo	eness to step	on Ŵ/O	0.00 DAS 27 0.00 9-89 13 Q	25			(101 Cons		·	<u>.</u>		

Work Orde		264		*912	64*						Page 3	
Item ID: Revision ID: Item Name:	647.0112 Strut Bracket			Accept	*N900	040	10)* s	Setup Sta	1 7	S1* S2*	
Start Date: Required Date: Reference:	10/04/12 10/31/12	Start Qty: 98.00 Req'd Qty: 98.00	*98* *98*		Cust Item :	ID:					. 17	
Approvals:	Process Pla	n:	Date:	Tooling: _	D	ate:	_	F	Run Sta	1/1	R1*	
	QC:		Date:	SPC (Y/N):	D	ate:			Sto	*N	R2*	
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
150 SprayPaint Spray Painting	·	Memo PRIME AS P	ER DWG NOTE 6	0.00				101	Ø	<u></u>	13-9-29	
		PR-148 PRIN	MER BATCH: 12602	<u>2</u> .								
*160		QC14- Inspect Spray Pain	t	0.00				101			845 12 10	1 21
QC Quality Control		Memo		0.00				_101_			<u> </u>)·0)
170			(4876					•				
170 *170* Packaging		Identify as per dwg & Stoo	ck Location: 71393	0.00				101			33 13	L-10-0

IDENTIFY AS PER APICAL MPP-120 BY STAMPING P# AND REV

Packaging

Work Orde		264		*912	264*						Page 4
Item ID: Revision ID: Item Name:	647.0112 Strut Bracket			*N900040			100* Setup			1	JS1* JS2*
Start Date: Required Date: Reference:	10/04/12 10/31/12	Start Qty: 98.00 Req'd Qty: 98.00	*98* *98*		Cust Item I Customer:	D:				•	
Approvals:	Process Pla	an:	Date:	Tooling: SPC (Y/N):		ite:		Ru	n Sta	op *	NR1* NR2*
Sequence ID/ Work Center II 180 *180* QC Quality Control)	Operation Description QC21- Final Inspection - Memo	Work Order Release	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code		Reject Qty	Reject Number Rm.	=



Picklist Print

October-05-12 9:11:55 AM

Page 1

Work Order ID:

91264

Parent Item:

647.0112

Parent Item Name:

Strut Bracket

Start Date: 10/04/12

Required Date: 10/31/12

Start Qty: 98.00


Required Qty: 98.00

Comments:


IPP REV:A 12.08.14 NEW ISSUE DD VERF:JFS


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S14GA 304SS sheet .080		Purchased	No			100	sf	40.7400	0.0325	3,3526316 3.5	· ·		Jm 12-1
				Location		Loc Qty	Loc	c Code					
*				MAT020		40.74							
`				1179	33	3.6							
				1192	76	37.14			119	276			


æ.





SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 91264 MLJ

















DART AEROSPACE LTD	Work Order:	91264
Description: Strut Bracket	Part Number:	647.0112
Inspection Dwg: 647.0100 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

Drawing Dimension	Tolerance	Actual Dimension	Accept	Re'ect	Method of Inspection	Comments
Ø0.177"	+0.005"	0.178"	<u> </u>		Ů	mmoi
0.300"	11-0.010"	0.309"	. –		V	
0.900"	11-0.010"	0.904"	_		V	
1.50"	t1- 0.030"	1.516"	_		V	
3.121	41-0.010"	3.121"	_		1/	
1.006"	11-0.010	1.006"	_		V	
0.080"	11-0.010"	0.075"	~		V	
					÷	
				1 .		
7						
				<u> </u>		
			<u> </u>			
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		<u> </u>				
				 		A STATE OF THE STA

Measured by: JM	Audited by:	SMB	P	reliminary Approval:	
Date: 12-10-13	Date:	12/0.16		Date:	

Rev	Date	Change			Revised by	Approved
E	10.04.14	Added preliminary app	proval		KJ	